





Version	Date	Change/	additions additions
01.30.00	Jun, 9th 2020	■ Race Sim	ulators handling
		■ Added H	our/Date info from GPS tracks
		■ Added re	ference speed used to calculate odometers
		Improved	d k-line handling
		External n	nodules
		No change	S
01.28.20	Dec, 4th 2019	■ Fixed issu	ue on CAN bus off handling of ECU CAN line
		Improved	d synchronization between data from GPS and local data acquisition
		External n	nodules
		<b>35.64</b>	GPS Module
			■ Improved synchronization between data from GPS and local data acquisition
01.28.10	Jul, 5th 2019	■ Fixed bug	g in Channel Expansion/TCHub firmware that caused blinking in Race Studio 3 Live Measures
		External n	nodules
		<b>40.63</b>	Channel Expansion/TC Hub
			■ Fixed bug that caused blinking in Race Studio 3 Live Measures
01.28.08	Jun, 12th 2019	■ Fixed CA	N protocols with multiplex frames
		External n	nodules
		<b>40.62</b>	Channel Expansion/TC Hub
		<b>35.61</b>	GPS Module
01.28.03	Feb, 12th 2019	Fixed display artifacts in measures value cleaning	
		External n	nodules
		<b>01.26.49</b>	GS-Dash  Measures timeout improved
			Spansion support
			■ Fix data recall synchronization issue
		<b>01.26.48</b>	Memory Module
			■ Improved support for various models of SD cards
		<b>02.26.51</b>	Shift Light Module
		Ma -l-	■ Fixed issues with some ECUs
		No change	s for the other modules







Version	Date	Change/a	additions
01.26.46	Dec, 5th 2018	■ Added ma	anagement of Shift Light Module
		External m	odules
		No changes	;
01.26.42	Oct, 30th 2018	■ Support fo	or CAN Optical Lap (IRM_42)
		■ Set Bright	ness Mode using Remote button fix
		CAN Bus	120 Ohm Resistor setting fix
		Optical Be	eacon blind time fix
		External m	odules
		No changes	3
01.26.38	Oct, 5th 2018	<ul><li>Added po</li></ul>	ossibility to force channels in Online
		■ Fixed bug	g on Digital output priority handling
		External m	odules
		No changes	5
01.26.28	Apr, 12th 2018	■ Fixed bug	g in remote display configuration
		External m	odules
		■ 01.26.22	Memory Module
		<b>01.26.28</b>	•
		■ 01.26.28	Formula Steering Wheel 3
		■ 35.58	GPS Module
		<b>25.47</b>	Lambda
		<b>40.61</b>	Channel Expansion/TC Hub
		<b>70.03</b>	Remote buttons interface







Version

### **EVO5** Release history

Date

Page 3

01.26.25	Jan 11th 2018	<ul> <li>Fixed bug when the Start Data Recording standard condition is configured: in some conditions it caused not recorded data</li> <li>Fixed bug in volume sensors with gallons unit measure</li> </ul>	
		External m	odules
		■ 01.26.22	Memory Module
		<b>01.26.22</b>	GS-Dash
		<b>01.26.22</b>	Formula Steering Wheel 3
		■ 35.58	GPS Module
		<b>25.47</b>	Lambda
		<b>40.61</b>	Channel Expansion/TC Hub
		<b>70.03</b>	Remote buttons interface
01.26.24	Nov 14th 2017	■ Fix lockup	o at power up for some devices
		External m	odules
		■ 01.26.22	Memory Module
		<b>01.26.22</b>	GS-Dash
		<b>01.26.22</b>	Formula Steering Wheel 3
		■ 35.58	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub
		<b>70.03</b>	Remote buttons interface

**01.26.23** Oct 24th 2017

- Support for CAN builder ID mask feature
- Consumed fuel channel

Change/additions

- Fix: Pulse per wheel revolution setting not working for Speed1 or Speed2 digital inputs
- Fix: wrong order of operands in bias math channel

### **External modules**

- **01.26.22** Memory Module
- **01.26.22** GS-Dash
- **01.26.22** Formula Steering Wheel 3
- **35.58** GPS Module **25.46** Lambda
- 40.60 Channel Expansion/TC Hub70.03 Remote buttons interface







Version	Date	Change/a	additions
01.26.14	Jul 7th 2017	Improved CAN management: more reliability in firmup and configuration transmission	
		External m	odules
			Memory Module
		<b>=</b> 01.26.14	
			Formula Steering Wheel 3
		■ 35.58	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed
		<b>70.03</b>	Remote buttons interface
01.26.08	Jun 20th 2017	Memory	Module support
		External m	nodules
		■ 01.26.08	Memory Module
		■ 01.26.08	GS-Dash
		<b>01.26.08</b>	Formula Steering Wheel 3
		■ 35.58	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed
		<b>70.01</b>	Remote buttons interface
01.24.56	Jun 1st 2017	■ Fixed roll	ing lap time on GS-Dash and Formula Steering Wheel 3
		External m	nodules
		■ 01.24.56	GS-Dash
		<b>01.24.56</b>	Formula Steering Wheel 3
		<b>35.58</b>	GPS Module
		<b>25.46</b>	Lambda
		<b>40.60</b>	Channel Expansion/TC Hub: minor bug fixed
		<b>70.01</b>	Remote buttons interface
01.24.54	May 19th 2017	Includes	firmware GPS v 35.58.00 that fixes data synchronization with SmartyCam HD
		External m	nodules
		<b>01.24.54</b>	GS-Dash
		<b>= 01.24.54</b>	Formula Steering Wheel 3
		<b>35.58</b>	GPS Module







Version	Date	Change/additions	
		<b>25.46</b> Lambda	
		■ 40.60 Channel Expansion/TC Hub: minor bug fixed	
		■ <b>70.01</b> Remote buttons interface	
01.24.52	May 18th 2017	■ Fixed GPS Data visualization on GS-Dash and Formula Steering Wheel 3	
01.24.32	Way 16th 2017		
		External modules	
		<b>01.24.52</b> GS-Dash	
		<b>01.24.52</b> Formula Steering Wheel 3	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		<b>40.60</b> Channel Expansion/TC Hub: minor bug fixed	
		■ 70.01 Remote buttons interface	
01.24.45	Apr 19th 2017	■ Fixed bug in AiM digital speed channels when 'Ang Velocity' is selected (i.e. RPM setting)	
		External modules	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		■ 40.56 Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	
01.24.38	Apr. 5th 2017	<ul> <li>Support for Formula Steering Wheel 3 configuration</li> </ul>	
		External modules	
		■ <b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		■ 40.56 Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	
01.24.34	Mar 24th 2017	<ul> <li>Added GS-Dash management</li> </ul>	
		■ Improved accelerometer support: better filtering and uniform sign convention on various devices	
		External modules	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		■ 40.56 Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	







Version	Date	Change/additions	
01.24.00	Jan 26th 2017	Fixed issue that caused CAN network malfunction when remote button device is in the network	
		External modules	
		■ 35.56 GPS Module	
		<b>25.46</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ 70.01 Remote buttons interface	
01.22.99	Jan 19th 2017	<ul> <li>Added management of GPS position accuracy measure for CAN output</li> </ul>	
		External modules	
		<b>35.56</b> GPS Module	
		<b>25.46</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ 70.01 Remote buttons interface	
01.22.94	Dec 5th 2016	■ No changes	
		External modules	
		<b>35.56</b> GPS Module	
		■ 25.46 Lambda: fixed bug that caused shifted lambda samples	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	
01.22.92	Nov 29th 2016	■ Fixed bug which prevented editing of Wi-Fi and User parameters from RS3	
		<ul> <li>Minor improvements</li> </ul>	
		External modules	
		■ 35.56 GPS Module: improvements in GPS measurements available to SmartyCam overlay	
		<b>25.44</b> Lambda	
		<b>40.56</b> Channel Expansion/TC Hub	
		■ <b>70.01</b> Remote buttons interface	







Version	Date	Change/additions
01.22.86	Nov 15th 2016	■ Added IRM CAN LAP support
		External modules
		■ 35.54 GPS Module: improved satellites fix
		<b>25.44</b> Lambda: added keep alive support
		■ 40.56 Channel Expansion/TC Hub
		■ <b>70.01</b> Remote buttons interface
01.22.82	Oct 11th 2016	Speed up USB transfer
		Fixed bug in GPS lap management that in some cases caused loss of laps detected
		External modules
		<b>35.50</b> GPS Module
		<b>25.42</b> Lambda
		<b>40.56</b> Channel Expansion/TC Hub: improved analogic channels acquisition
		■ <b>70.01</b> Remote buttons interface
01.22.74	Sep 15th 2016	■ Fixed alarms functionality based on acquisition channels under encryption
		External modules
		<b>35.50</b> GPS Module
		<b>25.42</b> Lambda
		■ 40.55 Channel Expansion/TC Hub
		■ <b>70.01</b> Remote buttons interface
01.22.60	Jul 25th 2016	Fixed: Wi-Fi troubles with TP-link routers
		Fixed: alarm hysteresis condition
		Minor bugfixes and improvements
		External modules
		■ <b>35.50</b> GPS Module
		<b>25.42</b> Lambda
		■ 40.55 Channel Expansion/TC Hub
		■ <b>70.01</b> Remote buttons interface







Version	Date	Change/additions
01.20.68	Jul 1st 2016	Fixed: handling of enabling /disabling of CAN termination resistance
		External modules
		<b>35.50</b> GPS Module
		<b>25.42</b> Lambda (fixed issues with channels configured at 5Hz)
		■ 40.55 Channel Expansion/TC Hub: improvement in measurements accuracy
		■ <b>70.01</b> Remote buttons interface
01.20.66	Apr 19th 2016	<ul><li>CAN output support</li></ul>
		External modules
		<b>35.50</b> GPS Module
		<b>25.42</b> Lambda (fixed issues with channels configured at 5Hz)
		■ 40.55 Channel Expansion/TC Hub: improvement in measurements accuracy
		■ <b>70.01</b> Remote buttons interface
01.20.63	Mar 11th 2016	Fixed issue on ECU channels right after a configuration update
		Fixed issue in start reco via custom formula
		External modules
		■ 35.50 GPS Module
		<b>25.42</b> Lambda (fixed issues with channels configured at 5Hz)
		<b>40.54</b> Channel Expansion/TC Hub
		■ 70.01 Remote buttons interface
01.20.62	Mar 9th 2016	■ Improvements in Wi-Fi and measurements for SmartyCam
		■ Fixed bug in Custom Position Sensor (the measure was multiplied by 1000)
		External modules
		<b>35.50</b> GPS Module
		= 25.40 Lambda
		<ul><li>40.54 Channel Expansion/TC Hub</li><li>70.01 Remote buttons interface</li></ul>
		- 70.01 Remote puttons interface
01.20.61	Feb 26th 2016	■ First production version