





| Version | Date | Change/ | additions |
|----------|----------------|-----------------|--|
| 01.30.00 | Jun, 9th 2020 | ■ Race Sim | ulators handling |
| | | Added H | our/Date info from GPS tracks |
| | | ■ Added re | ference speed used to calculate odometers |
| | | Improved | d k-line handling |
| | | External n | nodules |
| | | No change | s |
| | | | |
| 01.28.20 | Dec, 4th 2019 | Improved | d setting of LEDs brightness |
| | | ■ Fixed issu | ue on CAN bus off handling of ECU CAN line |
| | | Improved | d synchronization between data from GPS and local data acquisition |
| | | External m | nodules |
| | | ■ 35.64 | GPS Module |
| | | | ■ Improved synchronization between data from GPS and local data acquisition |
| 01 00 10 | I.J. 545 2010 | = Ft | and the second formation of the formation that are considered in the second sec |
| 01.28.10 | Jul, 5th 2019 | | g in Channel Expansion/TCHub firmware that caused blinking in Race Studio 3 Live Measures |
| | | External m | |
| | | 40.63 | Channel Expansion/TC Hub |
| | | | ■ Fixed bug that caused blinking in Race Studio 3 Live Measures |
| 01.28.08 | Jun, 12th 2019 | ■ Fixed CA | N protocols with multiplex frames |
| | | External m | nodules |
| | | 40.62 | Channel Expansion/TC Hub |
| | | 35.61 | GPS Module |
| | | | |
| 01.28.03 | Feb, 12th 2019 | ■ Fixed dis | play artifacts in measures value cleaning |
| | | External m | nodules |
| | | 01.26.49 | |
| | | | Measures timeout improvedSpansion support |
| | | | Fix data recall synchronization issue |
| | | ■ 02.26.51 | Shift Light Module |
| | | | ■ Fixed issues with some ECUs |
| | | No change | s for the other modules |
| | | | |







| Version | Date | Change/additions |
|----------|----------------|--|
| 01.26.46 | Dec, 5th 2018 | ■ Added management of Shift Light Module |
| | | Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable) |
| | | External modules |
| | | No changes |
| 01.26.38 | Oct, 5th 2018 | Added possibility to force channels in Online |
| | | Fixed bug on Digital output priority handling |
| | | External modules |
| | | No changes |
| | | |
| 01.26.28 | Apr, 12th 2018 | No changes |
| | | |
| 01.26.25 | Jan 11th 2018 | Fixed bug when the Start Data Recording standard condition is configured: in some conditions it caused not recorded data |
| | | Fixed bug in volume sensors with gallons unit measure |
| | | External modules |
| | | ■ 35.58 GPS Module |
| | | 25.47 Lambda |
| | | ■ 40.61 Channel Expansion/TC Hub |
| | | ■ 70.03 Remote buttons interface |
| | | |
| 01.26.24 | Nov 14th 2017 | No changes |
| | | |
| 01.26.23 | Oct 24th 2017 | ■ Support for CAN builder ID mask feature |
| | | ■ Consumed fuel channel |
| | | Fix: Pulse per wheel revolution setting not working for Speed1 or Speed2 digital inputs |
| | | Fix: wrong order of operands in bias math channel |
| | | External modules |
| | | 35.58 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.60 Channel Expansion/TC Hub |
| | | ■ 70.03 Remote buttons interface |
| | | |







| Version | Date | Change/additions |
|----------|---------------|--|
| 01.26.14 | Jul 7th 2017 | ■ Improved CAN management: more reliability in firmup and configuration transmission |
| | | External modules |
| | | 35.58 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.60 Channel Expansion/TC Hub: minor bugs fixed |
| | | ■ 70.03 Remote buttons interface |
| 01.26.08 | Jun 20th 2017 | ■ No changes |
| | | External modules |
| | | 35.58 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.60 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| | | |
| 01.24.54 | May 19th 2017 | ■ Includes firmware GPS v 35.58.00 that fixes data synchronization with SmartyCam HD |
| | | External modules |
| | | 35.58 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.60 Channel Expansion/TC Hub: minor bugs fixed |
| | | 70.01 Remote buttons interface |
| 01.24.52 | May 18th 2017 | Added support for new display configuration (RaceStudio3 v 3.15.00 required) |
| | | External modules |
| | | ■ 35.56 GPS Module |
| | | ■ 25.46 Lambda |
| | | ■ 40.60 Channel Expansion/TC Hub: minor bugs fixed |
| | | ■ 70.01 Remote buttons interface |
| | | |
| 01.24.14 | Mar 24th 2017 | Fixed bug that caused no data from channels with hysteresis |
| | | External modules |
| | | 35.56 GPS Module |
| | | 25.46 Lambda |
| | | 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| | | |







| Version | Date | Change/additions |
|----------|---------------|--|
| 01.24.13 | Mar 24th 2017 | Improved accelerometer support: better filtering and uniform sign convention on various devices |
| | | Fixed occasional spikes on accelerometer channels |
| | | External modules |
| | | ■ 35.56 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| 01.24.00 | Jan 26th 2017 | ■ Fixed issue that caused CAN network malfunction when remote button device is in the network |
| | | External modules |
| | | ■ 35.56 GPS Module |
| | | 25.46 Lambda |
| | | 40.56 Channel Expansion/TC Hub |
| | | 70.01 Remote buttons interface |
| 01.22.99 | Jan 19th 2017 | Added management of GPS position accuracy measure for display and CAN output |
| | | Fixed bug in "Backlight" menu voice (icon missed) |
| | | External modules |
| | | ■ 35.56 GPS Module |
| | | 25.46 Lambda |
| | | ■ 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| | | |
| 01.22.94 | Dec 5th 2016 | ■ No changes |
| | | External modules |
| | | 35.56 GPS Module |
| | | ■ 25.46 Lambda: fixed bug that caused shifted lambda samples |
| | | ■ 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| | | |







| Version | Date | Change/additions |
|----------|---------------|--|
| 01.22.92 | Nov 29th 2016 | Minor improvements |
| | | External modules |
| | | 35.56 GPS Module: improvements in GPS measurements available to SmartyCam overlay |
| | | 25.44 Lambda |
| | | ■ 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| 01.22.86 | Nov 15th 2016 | Added IRM CAN LAP support |
| | | Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher. |
| | | External modules |
| | | 35.54 GPS Module: improved satellites fix |
| | | 25.44 Lambda: added keep alive support |
| | | 40.56 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| | | |
| 01.22.82 | Oct 11th 2016 | ■ Speed up USB transfer |
| | | Speed up display pages loading at the startup |
| | | Fixed bug in GPS lap management that in some cases caused loss of laps detected |
| | | Warning: this firmware release requires Race Studio 3 ver. 3.10.10 or higher. |
| | | External modules |
| | | 35.50 GPS Module |
| | | 25.42 Lambda |
| | | 40.56 Channel Expansion/TC Hub: improved analogic channels acquisition |
| | | 70.01 Remote buttons interface |
| | | |
| 01.22.74 | Sep 15th 2016 | ■ Fixed alarms functionality based on acquisition channels under encryption |
| | | Fixed message alarms that sometimes were partially or totally erased |
| | | Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. |
| | | External modules |
| | | 35.50 GPS Module |
| | | 25.42 Lambda |
| | | 40.55 Channel Expansion/TC Hub |
| | | 70.01 Remote buttons interface |
| | | |







Page 6

| Varsian | Data | Change /additions |
|----------|---------------|---|
| Version | Date | Change/additions |
| 01.22.60 | Jul 25th 2016 | Fixed: clear alarm by remote buttons |
| | | Fixed: alarm hysteresis condition |
| | | Minor bugfixes and improvements |
| | | Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. |
| | | External modules |
| | | 35.50 GPS Module |
| | | 25.42 Lambda |
| | | ■ 40.55 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| 01.22.16 | Jun 17th 2016 | ■ Fixed display issue when 8 pages are configured |
| | | ■ Fixed bug on Shift Light management |
| | | Minor improvements |
| | | Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. |
| | | External modules |
| | | 35.50 GPS Module |
| | | 25.42 Lambda |
| | | ■ 40.55 Channel Expansion/TC Hub |
| | | ■ 70.01 Remote buttons interface |
| 01.22.14 | Jun 10th 2016 | New track management, compatible with the MyChron5 one |
| | | ■ Test data recall |
| | | Warning: this firmware release requires Race Studio 3 ver, 3.10.10 or higher. |
| | | External modules |
| | | 35.50 GPS Module |
| | | 25.42 Lambd |
| | | ■ 40.55 Channel Expansion/TC Hub |

■ **70.01** Remote buttons interface