

Version	Date	Change/additions
02.32.81	Jul, 17th 2020	■ Fixed RPM issue due to wrong RPM factor handling
		External modules
		No changes
02.32.72	May, 22nd 2020	■ Simulators handling
		Added Hour/Date info from GPS tracks
		Added reference speed used to calculate odometers
		External modules
		No changes
02.32.55	Apr, 23rd 2020	■ General speed up in transmitting configuration
	• •	■ Solved missing timeout on ECU channels for some serial protocol (RS232 and K-line) (AB#59)
		■ Improved track visualization
		■ Digital channels: bug fix on RPM input capture
		■ Fixed alarms based on BestDiff time
		External modules
		No changes
02.32.12	Feb, 10th 2020	■ Fixed bug that didn't enable the display page after rear camera visualization
		External modules
		No changes
02.32.09	Oct, 17th 2019	■ First Release including the new graphic engine which has the following improvements:
		■ Faster boot time
		Boot time independent from the number of configured pages
		Improvement in font visualization quality
		<ul><li>Resizable fonts</li><li>Colorable icons</li></ul>
		This firmware release is compatible ***ONLY*** with the Race Studio 3 releases starting
		from the 03.30.00
		External modules
		<b>2.30.16</b> Shift Light Module: support for the new software release (v03.30.00)
		■ 35.64 GPS Module: improved GPS data synchronization







Version	Date	Change/additions
02.30.12	Jul, 11th 2019	<ul> <li>Fixed display visualization when large font is used for GEAR measure</li> <li>Fixed bug on Trigger Commands when the action is configured as "Reset Alarms Command"</li> <li>External modules</li> <li>40.63 Channel Expansion/TC Hub: no changes for these loggers</li> </ul>
02.30.10	Jun, 12th 2019	<ul> <li>Fixed bug locking the device in data recall</li> <li>AIM CAN network improvements</li> <li>Fixed the calibration of the Expansion channels</li> <li>External modules</li> <li>40.62 Channel Expansion/TC Hub</li> <li>35.61 GPS Module</li> </ul>
02.30.06	May, 23rd 2019	<ul> <li>Fixed reset gear calculation</li> <li>Popup management:</li> <li>Background color configurable from RS3</li> <li>Txt color configurable from RS3</li> <li>External modules</li> <li>No changes</li> </ul>
02.30.02	Apr, 19th 2019	<ul> <li>Improved K-line protocols management</li> <li>Added open tracks management</li> <li>External modules</li> <li>No changes</li> </ul>
02.26.57	Mar, 22nd 2019	■ Fix speed indication in miles for analog controls  External modules  No changes



Version	Date	Change/additions
02.26.55	Mar, 14th 2019	<ul> <li>Improved ADC accuracy</li> <li>GPS page skipped when the vehicle is moving</li> <li>Increased channel frequencies for selected ECUs (in particular K-line- and RS232- based ones)</li> <li>Fix bug on clear alarm by keypress</li> <li>Fix display bug which could lead to device resets with heavy configurations (multiple pages)</li> <li>External modules</li> <li>No changes</li> </ul>
02.26.53	Feb, 14th 2019	<ul> <li>Fixed inertial platform orientation</li> <li>External modules</li> <li>02.26.51 Shift Light Module         <ul> <li>Fixed issues with some ECUs</li> </ul> </li> <li>No changes for the other modules</li> </ul>
02.26.50	Jan, 18th 2019	<ul> <li>Digital inputs</li> <li>Support for Memory Module, Strada Logger and GS-Dash</li> <li>ECU: support Adaptronics and Motec M4 ECU drivers</li> <li>External modules</li> <li>01.26.48 Memory Module and Strada Logger</li> <li>01.26.47 GS-Dash</li> </ul>
02.26.35	Dec, 5th 2018	<ul> <li>Added management of Shift Light Module</li> <li>Added the support for auto brightness levels configuration (day brightness level, night brightness level and threshold are now fully configurable)</li> <li>External modules</li> <li>No changes</li> </ul>
02.26.12	Oct, 30th 2018	<ul> <li>Support for CAN Optical Lap (IRM_42)</li> <li>CAN network fixes</li> <li>100Hz CAN output management</li> <li>External modules</li> <li>No changes</li> </ul>







Version	Date	Change/additions
02.26.08	Oct, 15th 2018	■ Improved synchronization of GPS data
		External modules
		<b>35.60</b> GPS Module
		<b>25.47</b> Lambda
		■ 40.61 Channel Expansion/TC Hub
		■ <b>70.03</b> Remote buttons interface
02.26.06	Oct, 5th 2018	■ Fixed bug on Digital output priority handling
02.26.01	Oct, 1st 2018	Added support for rear cam and rear cam configuration menu
		■ Fix on units of measure visualization
02.24.04	Sep, 21st 2018	■ Support for RS232 protocols
02.22.96	Sep, 11th 2018	■ Fixed potentiometers calibration
		Improved display management when ECU CAN stream has very few fields
02.22.93	Sep, 4th 2018	■ Support for fuel set/reset using Race Studio 3
		Fix on visualized unit of measure
02.22.81	Jul, 27th 2018	■ Fixed Remote button interface compatibility
		■ Fixed multiplexed CAN protocols management