





Version	Date	Change/additions
01.30.00	Jun 15th 2020	■ Added Hour/Date info from GPS tracks
		External modules
		No changes
01.28.32	Mar 19th 2020	Fixed magnetical lap
		External modules
		No changes
01.28.31	Mar 18th 2020	■ Improved synchronization between local and GPS data
		 Added possibility to revert the sign of Steering calibration when the sensor is configured
		for Mychron Expansion
		Added missing brake pressure sensors in supported sensors list for Mychron Expansion
		■ Fixed GPS data sent to SMC(before sent @1Hz, now @10 Hz)
		■ Improved track rendering
		External modules
		No changes
01.28.08	Jul 5th 2019	■ Fixed firmup to have the same firmware version in Oval and Road Mode
		External modules
		No changes
01.28.06	Jun 12th 2019	Improved visualization of the temperature channels in custom pages
		External modules
		No changes
01.26.34	Sep 7th 2018	■ Fixed IRTemp controller management
		■ Removed the wrong "fuel used" reset in RS3 "Counters" page
		External modules
		No changes
01.26.33	Jun 11th 2018	 Fixed bug that sometimes caused bad GPS data acquisition and consequently problems in the data shown in Analysis
		External modules
		No changes







Version	Date	Change/additions
01.24.62	Jun 20th 2017	 Reintroduced in "LapTime Setup" the Menu voice "Beacon Mode" for Automatic or Manual Mode (european systems).
		External modules
		No changes
01.24.60	Jun 13th 2017	 Improved filtering in temperatures management
		External modules
		No changes
01.24.40	Apr 11th 2017	 Added oval track support
		Fixed bug in the bottom right measure of a display custom page that sometimes was dirty
		Reinforced odometers management by RS3 that in some cases caused issue on M5 menu
		External modules
		No changes
01.22.99	Jan 19th 2017	■ For M5 USA, reintroduced in data recall the histogram laps page only for road racing tests
		External modules
		No changes
01.22.98	Dec 22nd 2016	 Added IRTemperature Controller support
		 Added in custom page setup on the bottom right field the possibility to choose any measure available, not the lap time measures only
		External modules
		25.46 Lambda
		■ 48.18 MyChron Expansion/IR Temperature Controller: added IR Temperature Controller support
01.22.94	Dec 5th 2016	■ No changes
		External modules
		25.46 Lambda: Fixed bug that caused shifted lambda samples
		48.15 MyChron Expansion
01.22.92	Nov 29th 2016	■ Fixed bug which prevented editing of Wi-Fi and User parameters from RS3
		Minor improvements







Version	Date	Change/additions
01.22.86	Nov 15th 2016	■ Added IRM CAN LAP support
01.22.84	Oct 13th 2016	■ Fixed bug in GPS lap management that in some cases caused loss of laps detected
		■ Fixed bug on Lambda value to SmartyCam HD
01.22.70	Sep 8th 2016	■ Improved display management in case of strong electro-magnetical noise
		■ Improved analogic channels acquisition for Mychron Expansion
		■ Fixed conversion of TEXENSE INKFL 0-150°C sensor for Mychron Expansion
01.22.60	Jul 25th 2016	■ Fixed: speed and gear in SC measures
		■ Fixed: Wi-Fi troubles with TP-link routers
		■ Minor bugfixes and improvements
01.22.54	Jul 15th 2016	■ Fixed an issue in version 01.22.52 only: time and date update may not work
01.22.52	Jul 12th 2016	■ Fixed predictive and +/-Best time display visualization
		■ Fixed Led Bar OFF mode
		Japanese language update
		Minor bugfixes and improvements
01.22.44	Jun 17th 2016	■ The default pages can now show the external temperatures if the internal ones are not connected
01122111	3411 17 411 2010	■ Increased min voltage gap in expansion sensors calibration
		■ Improved menu for Mychron Expansion sensors setup
		■ Improved GPS lap generation in case of finish line is too close to another part of the track
		Added GPS info to SmartyCam (satellites status, date and time)
		■ Added Japanese language support
01.21.10	May 30th 2016	Fixed minor issue in applying shiftlight configuration
		■ Fixed display issue visible only in RPM_FACTOR X2
		■ Fixed issue in GPS data time stamping that in some cases caused loss GPS data in RS2 Analysis
		Other minor improvements and bugfixes







Version	Date	Change/additions
01.21.07	May 3rd 2016	Fixed bug on Mychron Expansion contactless sensors calibration that in some cases was very difficult
		Fixed bug on temperatures visualization in custom pages
		Changed name of Mychron Expansion generic 0-100% potentiometer sensor that caused incompatibility with mathematical channels functionality in Race Studio Analysis
		Added translation in language for some menu voices
		■ Improved Wi-Fi communication
01.21.04	Apr 21st 2016	■ Fixed bug in unit measure conversion for temperatures showed on the dash
01.21.02	Apr 20th 2016	■ Manages MyChron Expansion and Lambda controller
		■ Wi-Fi now is only in AUTO or OFF Mode
01.20.36	Feb 26th 2016	■ Introduced custom tracks deletion
		■ Improved Lap Time management
01.20.30	Feb 21st 2016	■ Fixed bug on water temp threshold alarm (in F degrees)
01.20.28	Feb 16th 2016	Fixed bug menu selection track when there are device tracks created
01.20.27	Feb 11th 2016	Added automatic track detection (for closed tracks), creating new device-generated tracks
		■ Fixed Time Zone +12 that was missed in menu
01.20.04	Jan 29th 2016	■ Fixed bug GPS speed not shown by SmartyCam
		■ Battery: improved status display
		■ RPM: support for factor /3
01.20.03	Jan 22nd 2016	■ Danish language support
01120105	3411 ZZ114 Z010	Fix german language strings
		■ Fix random resets that could be generated when displaying popup (like low battery warnings)
01.20.01	Jan 8th 2016	■ Fixed "Usr 1" odometer menu issues
		■ Fixed internal battery value





June, 15th 2020

MyChron5 Release history

Version	Date	Change/additions
01.20.00	Dec 23rd 2015	■ Added RPM factor in RPM setup
01.19.27	Dec 21st 2015	Dutch language support
01.19.26	Dec 16th 2015	■ First production version of MyChron5 (supporting GPS Manager3 tracks format)